### INSPECTION SUPPORT SERVICES DIVISION

Batch Plants & Civil Testing Unit WC -1134B, Al-Midra Tower, North Park Office Complex 4, Dhahran Telephone: 880-1847, Fax: 875-8330 June 1, 2016

BP&CTU: L-229.2016

EVALUATION OF INTERNAL RMC BATCH PLANT LAB TECHNICIAN

Mohammed S. Al-Subhi, Supervisor

ID/SAPID/DPIS

WC-1131B, Flr.11 West Wing, Al Midra Tower Bldg.3303, Dhahran

Email: MOHAMED.SUBHI@ARAMCO.COM

Tel: +966 13 880-1894

Attention: Al Ghamdi, Jamaan A,

Material Description:	Material SAP 9COM <b>6000000453</b> : Ready Mix Concrete from SAPMT & APIU proposed Batch Plants to 09-SAMSS-097
Manufacturer:	AL SHALAWI RMC Batch Plant: SHALAWI RMC Batch Plant # 1 & Support Facilities
Plant Location:	2 <sup>nd</sup> Industrial City, Dammam Saudi Arabia
BI/CN:	28-10011/6600036079
Contractor:	AL SHALAWI Intl Holding Co. for Trading Contracting P.O.Box 2853, Al Khobar 31952
	18 CONSTRUCTION OF THE STATE OF
Project/Description:	Dammam Home Ownership Lots Development Increment II, East Dammam
Project/Description: References:	

The results are as follows:

Ready Mix Concrete Batch Plant Internal Laboratory Technician is **Approved.** 

See Attachments \*

Please initiate the necessary action

**Zahrani, Abdulwahid M,** Supervisor (A) Batch Plants & Civil Testing Unit

\*Attachments: (3 pages)

RAA/raa

cc: ID.ISSD.BP & CTU Manufacturer File, The Maintainer- ID.ISSD.BP & CTU Sharek Web Page

Saudi Aramco: Confidential

## ATTACHMENT 1 OF 3 PAGES TO BP&CTU-L-229.2016 EVALUATION REPORT

#### References:

- 1. Commercial Registration Number: **2051010618**, ISO 9001:2008 Compliant Certification No: **SA11/2267**, SAMPT submittal no. **28-10011-082**, with attached 12 pages of documents and associated personnel qualification records.
- 2. Saudi Aramco Standards: 09-SAMSS-097, SAEP 383/1150 & 1152, SAES-Q-001 and Saudi Aramco Basic Safety Handbook -2014 Edition.
- 3. International Industry Standards: ASTM C94, ASTM C1077, ACI 318/305R/311.5R and ISO 9001:2008.

#### Process Performed:

EVALUATION OF INTERNAL RMC BATCH PLANT LABORATORY TECHNICIAN FOR AL SHALAWI BP# 1 LOCATED IN 2<sup>nd</sup> INDUSTRIAL, DAMMAM/ AL SHALAWI HOLDING

As requested by the responsible SAPMT & APIU we evaluated the 12 pages submittals for the proposed new Internal Asphalt Batch Plant Lab Technician and associated documented information.

#### Our evaluation findings below;

Ref	Name	Requested Job Task Position	Evaluation findings	Recommendations
540	Shakeel Ahmed	Internal RMC Laboratory Technician	Competent	Approved

#### Recommendations:

- 1. Base on the results on examination and evaluation, the proposed new Internal Batch Plant Lab Technician is **Approved** for ready mix concrete batch plant specific project only.
- 2. This approval does not cover the job task outside the Ready Mix Concrete Batch Plant Quality control of the project, and as contractor shall be evaluated and approved by Area Project Inspection Unit as stated in Schedule Q (BI 28-10011) of the project.
- 3. Changes on the Manufacturers organizational chart for Concrete batch plant shall be updated and resubmitted to ID.ISSD.BP&CTU for evaluation and approval.
- 4. Absence due to annual vacation or emergency purposes of the approved internal BP Lab Technician shall be notified in writing 30 days in advance or 24 hours respectively to the Unit Supervisor of ID.ISSD.BP&CTU.

Please inform SAPMT.

Should you have any questions, please contact Remegio A. Abalos Jr at +966-13-880-1497 or email to REMEGIOJR.ABALOS@ARAMCO.COM

**Zahrani, Abdulwahid M,** Supervisor (A) Batch Plants & Civil Testing Unit

Attachments: (2 pages)

RAA/raa

cc: ID.ISSD.BP&CTU Manufacturer File, The Maintainer ID.ISSD.BP&CTU Sharek Web Page

Saudi Aramco: Confidential

# Attachment 2 of 3 pages to BP&CTU-L-229.2016 Request from SAPMT to SAPID/DAPIS

DCN#24.

# COMMUNITY & PUBLIC PROJECTS DEPARTMENT

CA & NA HO & U Projects Division

Bldg. 7013, Dammam Office Building

TRAN	SMITTAL
TIVAL	OWNTE
To Mohammed S. Al-Subhi, Supervisor (A) Inspection Department, Dhahran Project Inspection Unit WC – 1131B, Floor 11, West Wing, Al – Midra Tower Building (Bldg. 3303), Tel. No. 880-1894 Attn: Jamaan A. Al-Ghamdi	From M.A. Otaibi, Lead Project Engineer CA & NA HO & U Projects Division R-10, Dammam Site Office(ED-II) Mob. 050-526-09014
BI / JO NO. : BI-28-10011  CONTACT NO. : 6600036079	PROJECT TITLE: Dammam Home Ownership Lots Development, Increment-II, East Dammam LOCATION: Dammam
No. of Copies:1 Ne	w Submittal
DES	CRIPTION
CV for proposed candidate: I	Lab. Technician (Concrete B/P): el Ahmad
REMARKS:	
Reply should be returned to us within 3 days from	the date of receipt via e-mail to:
rolando.pasamonte@aramco.com and/or mosaed	
Totalido, pasamonte (waramoo.com d. Moor meete	
	RECEIVED BY 02/03
	LECENTE STATE OF
TRANSMITTED BY:	Tille A Per
TRANSMITTED BY:  NAME : Abdullah AlGhamdi	NAME RECEIVED
The state of the s	NAME RECEIVED RECEIVED

Saudi Aramco: Company General Use

Saudi Aramco: Confidential



# Attachment 3 of 3 pages to BP&CTU-L-229.2016



# INSPECTION SUPPORT SERVICES DIVISION

Batch Plants & Civil Testing Unit WC 1122, 11<sup>TH</sup> FLOOR MIDRA, DHAHRAN Tel. +966138801583: Fax: +966138758330

# FINAL INTERVIEW, QC Lab/Field Technician (Concrete) (ASTM C94, ACI CP1/ISO 9001:2008, Clause 6, 09-SAMSS-097)

Location: Interviewer: Reason for Interview:					1.11	428,2016
	SHAREEL AHMED / SHALAW) RMC 2ND INDTI, OAMMAM		7			
Reason for Interview	A. OTAKES			Plant Fa	x No:	
receiour for mitterview.						
I. <u>Verification of</u>	Education, Ti	raining &	Work Ex	perience	<u>e:</u>	
No. Sc	Scope		Interviewees Answer (\) Good (\)   Fair (\)   Poor (\)		Accept (\)	Not Accept (X)
1.1		Good (1)	Pair ()	Poor (\)		
1.2						X
1.3						
1.4			/			
1.5			/		/	
Findings: LACKOF 8	EXPERENCE	IN OILS	GAS PDI	THOTE	/	
I. Verification of	QC Technicia	n Skills	& Abilitie	es:		
No.	000		viewees Answ	The state of the s	Accept ()	Not Accept (X)
		Good (\)	Fair (\)	Poor (\)		
2.1						
2.2					/	
2.3						
2.4						X
2.5					/	
2.0	TO HANDE 1					